

## JETTING SPECS:

**PSI TWIN PIPE 1997 INDY 700 XC**

STOCK - AIRBOX

03000FT.

Ideal Temperature Range(-10F to +20F)

|               | STOCK<br>PIPES     | PSI TWIN<br>STOCK CARBS | PSI TWIN<br>PIPE W/PORTING |
|---------------|--------------------|-------------------------|----------------------------|
| PILOT         | 40                 | 42                      | 42                         |
| AIRSCREW      | 3/4 TURN           | 1/2 TURN                | 1/2 TURN                   |
| SLIDE         | 6.5                | 6.5                     | 6.5                        |
| NEEDLE & POS. | R1370J-3RD         | R1370J-3RD              | R1370J-3RD                 |
| MAIN          | PTO/MAG<br>185/185 | PTO/MAG<br>200/205      | PTO/MAG<br>205/210         |

NOTE: STOCK AIRBOX WORKS WELL - NO GUTTING NECESSARY.

Above 30 degrees use 2nd clip position and lean 1 main jet.

## JETTING SPECS:

**PSI TWIN PIPE 1997 INDY RMK**

STOCK - AIRBOX

3000-6000FT.

|               | STOCK<br>PIPE      | PSI TWIN<br>PIPE   | PSI TWIN<br>PIPE W/PORTING |
|---------------|--------------------|--------------------|----------------------------|
| PILOT         | 55                 | 40                 | 45                         |
| AIRSCREW      | 3/4 TURN           | 3/8 TURN           | 3/8 TURN                   |
| SLIDE         | 5.0                | 6.5                | 6.5                        |
| NEEDLE & POS. | R1370J-3RD         | R1370J-3RD         | R1370J-3RD                 |
| MAIN          | PTO/MAG<br>162/162 | PTO/MAG<br>180/185 | PTO/MAG<br>185/190         |

**PSI TWIN PIPE 1997 INDY 700 RMK**

STOCK - AIRBOX

6000-10,000FT.

| RMK/SKS       | STOCK<br>PIPE      | PSI TWIN<br>PIPE   | PSI TWIN<br>PIPE W/PORTING |
|---------------|--------------------|--------------------|----------------------------|
| PILOT         | 55                 | 40                 | 45                         |
| AIRSCREW      | 3/4 TURN           | 1/2 TURN           | 1/2 TURN                   |
| SLIDE         | 5.0                | 6.5                | 6.5                        |
| NEEDLE & POS. | R1370J-3RD         | R1370J-3RD         | R1370J-3RD                 |
| MAIN          | PTO/MAG<br>158/158 | PTO/MAG<br>170/175 | PTO/MAG<br>175/180         |

\*For warm conditions or real hi-altitude changes you might need to use the 1st or 2nd needle clip position

## JETTING SPECS:

## PSI TWIN PIPE 1998-99 INDY 700 XC

STOCK - AIRBOX  
0-3000FT.

Ideal Temperature Range (-10F to +20F)

| STOCK XC      | STOCK PIPE         | PSI TWIN STOCK CARBS | PSI TWIN PIPE W/PORTING |
|---------------|--------------------|----------------------|-------------------------|
| PILOT         | 38                 | 38                   | * 40                    |
| AIRSCREW      | 3/4 TURN           | 1 TURN               | 1 TURN                  |
| SLIDE         | 6.0                | 6.0                  | 6.0                     |
| NEEDLE & POS. | R1368G-3RD         | R1368G-3RD           | R1368G-3RD              |
| MAIN          | PTO/MAG<br>185/185 | PTO/MAG<br>* 200/205 | PTO/MAG<br>* 205/210    |

NOTE: STOCK AIRBOX WORKS WELL - NO GUTTING NECESSARY.  
Above 30 degrees use 2nd clip position and 1 less main jet.

## JETTING SPECS:

## PSI TWIN PIPE 1998-99 INDY RMK

STOCK - AIRBOX  
3000-6000FT.

| RMK           | STOCK PIPE         | PSI TWIN PRO PIPE    | PSI SINGLE PRO PIPE W/PORTING |
|---------------|--------------------|----------------------|-------------------------------|
| PILOT         | 45                 | 45                   | 45                            |
| AIRSCREW      | 1/2 TURN           | 3/4 TURN             | 1/2 TURN                      |
| SLIDE         | 6.0                | 6.0                  | 6.0                           |
| NEEDLE & POS. | R1368G-3RD         | R1368G-3RD           | R1368G-3RD                    |
| MAIN          | PTO/MAG<br>175/175 | PTO/MAG<br>* 180/185 | PTO/MAG<br>* 190/195          |

## PSI TWIN PIPE 1998-99 INDY 700 RMK

STOCK - AIRBOX  
6000-10,000FT.

| RMK           | STOCK PIPE         | PSI TWIN PIPE        | PSI TWIN PIPE W/PORTING |
|---------------|--------------------|----------------------|-------------------------|
| PILOT         | 45                 | 45                   | 45                      |
| AIRSCREW      | 1/2 TURN           | 3/4 TURN             | 3/4 TURN                |
| SLIDE         | 6.0                | 6.0                  | 6.0                     |
| NEEDLE & POS. | R1368G-3RD         | R1368G-3RD           | R1368G-3RD              |
| MAIN          | PTO/MAG<br>165/165 | PTO/MAG<br>* 170/175 | PTO/MAG<br>* 175/180    |

\*For warm conditions or real hi-altitude changes you might need to use the 1st or 2nd needle clip position