

**SPECIAL SERVICE MESSAGES**

**1996/7 2008 F-SUPER DUTY - 6.4L AIR INDUCTION SNOW  
RESTRICTION**

**SOME 2008 6.4L F-SUPER DUTY VEHICLES, WHEN OPERATED IN  
HEAVY SNOW CONDITIONS, MAY EXPERIENCE A LACK OF POWER  
DURING ACCELERATION AND PERHAPS THE ILLUMINATION OF  
THE "CHECK AIR FILTER" MESSAGE IN DASH MESSAGE CENTER.  
THIS CONDITION MAY OCCUR WHEN THE AIR FILTER ELEMENT  
BECOMES PACKED WITH SNOW, THEREBY RESTRICTING  
REQUIRED AIR FLOW TO THE ENGINE. IN ORDER TO CORRECT  
THIS CONDITION, A WINTER GRILL COVER 8C3Z-19A414-A IS - No stock USA  
AVAILABLE FOR CUSTOMERS TO PURCHASE THAT FULLY COVERS  
THE OUTSIDE OF THE GRILL. TO ENSURE PROPER FUNCTION, THE  
WINTER GRILL COVER MUST BE INSTALLED PER THE INCLUDED  
INSTRUCTION SHEET. NOTE: THIS WINTER GRILL COVER MUST BE  
REMOVED WHEN TEMPERATURES ARE GREATER THAN 50F/10C  
(32F/0C WHEN TOWING) OR ENGINE DAMAGE CAN RESULT.  
EFFECTIVE DATE: 11/12/2007**

1-800-565-3673